

MR. EDVANATT S. PADMANABHA MENON (*Shertala I*): May I know whether it is a daily market.

MR. K. GEORGE (*Land Revenue and Income Tax Commissioner*): I claim notice.

Turavoor Tirumalai Devaswom Road.

188. *MR. EDAVANATT S. PADMANABHA MENON (*Shertala I*): Will the Government be pleased to state:

(a) whether they have received a representation from the Turavoor Tirumalai Devaswom Committee President that they are prepared to deposit the amount necessary for the acquisition of lands for the proposed Turavoor Tirumalai Devaswom road; and

(b) if the answer to part (a) is in the affirmative, what action has been taken on the same?

MR. G. B. E. TRUSCOTT (*Chief Engineer Roads, Buildings and Irrigation*): (a) Yes.

(b) A report has been received from the Chief Engineer and the question is under consideration.

The Kuttiyatodu bridge.

189. *MR. EDAVANATT S. PADMANABHA MENON (*Shertala I*): Will the Government be pleased to state:

(a) whether the Kuttiyatodu bridge is in order; and

(b) if the answer to part (a) is in the negative, what is the defect of it and when and how it happened?

MR. G. B. E. TRUSCOTT (*Chief Engineer, Roads, Buildings and Irrigation*): (a) Yes.

(b) In view of the answer to part (a), this does not arise.

Shertala-Arukutty road and Shertala-Tanneermukkom road.

190. *MR. EDAVANATT S. PADMANABHA MENON (*Shertala I*): Will the Government be pleased to state:

(a) whether any amount was allotted for the maintenance of Shertala-Arukutty road and Shertala-Tanneermukkom road in 1911; and

(b) if so, the amount spent per mile?

MR. G. B. E. TRUSCOTT (*Chief Engineer, Roads, Buildings and Irrigation*): (a) Yes.

(b) Rs. 198 and Rs. 314 on an average per mile for the Shertala-Arookutty road and Shertala-Tanneermukkom road respectively.

Irrigation tanks in Chirayinkil taluk.

191. *MR. K. PADMANABHAN (*Chirayinkil I*): Will the Government be pleased to give a list of irrigation tanks or *chiras* in Chirayinkil taluk with their survey numbers and *pakuthies* and state which of them are fit for use and which are in a state of disrepair?

MR. G. B. E. TRUSCOTT (*Chief Engineer, Roads, Buildings and Irrigation*): The member is referred to page 95 to 99 of the printed list attached to the Minor Irrigation Committee's report placed on the table of the Secretary to the Sri Mulam Assembly.